



AMERICAN MGB ASSOCIATION

TECHNICAL SECTIONS

VOLUME IV
(OCTAGON YEARS 2008 THRU 2018)

AVAILABLE BY EMAIL, IN CD AND IN PRINTED FORMATS

Volume I, II and III covering earlier publications also available from the AMGBA

PUBLISHED BY THE AMGBA
5433 N. ASHLAND AVE., CHICAGO, IL 60640 U.S.A.
phone/text: 773-769-7084

email: info@mgclub.org
www.mgclub.org or www.amgba.com



AMGBA TECHNICAL SECTIONS VOLUME IV

<u>PUBLICATION</u>	<u>PAGE</u>
2008 February	11
2008 May	17
2008 August	22
2008 October	25
2008 December	29
2009 March	33
2009 June	37
2009 September	42
2009 December	47
2010 March	52
2010 June	57
2010 September	61
2010 December	65
2011 March	68
2011 June	72
2011 September	77
2011 December	81
2012 March	83
2012 June	85
2012 September	87
2012 December	89
2013 March	91
2013 June	93
2013 September	95
2013 December	97
2014 March	99
2014 June	103
2014 September	106
2014 December	109
2015 March	112
2015 June	115
2015 September	118
2015 December	121
2016 March	124
2016 June	127
2016 September	130
2016 December	133
2017 March	135
2017 June	137
2017 September	141
2017 December	145
2018 March	149
2018 June	153

NOTE: Please note the ads that may appear here are reproduced as they originally appeared in that issue and therefore may be several years old and are not to be relied on for prices or information.

Nothing may be reproduced in whole or in part without the written permission of the publisher. The views of contributing writers are their own and not necessarily the views of the AMGBA. Readers are warned in following any advice given and no liability either express or implied is assumed by the advice or opinions given by individual contributors or the AMGBA.

AMGBA TECHNICAL SECTIONS VOLUME IV

PUBLICATION

PAGE

2018 September	157
2018 December	161
AMGBA Regalia/Store Order Form	165
AMGBA Membership Application	166

NOTE: Please note the ads that may appear here are reproduced as they originally appeared in that issue and therefore may be several years old and are not to be relied on for prices or information.

ARTICLE INDEX

Publication references in which AMGBA publication the article originally appeared and the year; the page number it was on and if a Question and Answer (Q&A), its position on the page and lastly the page number in this issue.

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION			PAGE NUMBER
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q&A</u>	<u>THIS ISSUE</u>
Body/Exterior				
Broken antenna replacement	2009 March	22		35
Door weather-stripping	2010 December	21	1	65
Floor board rust	2009 June	20	2	37
Floor panel and fender rust	2016 June	26	1	129
Grille replacement	2010 September	21	1	61
Installing a new top	2014 September	22	1	106
Rust preventatives on sills & floor pans	2009 September	23	1	45
Safety belt repair	2009 December	20	1	48
Overdrive emblems	2012 March	23	1	83
Rear bumper clamping bar	2013 June	23	2	93
Reinstalling window	2018 December	23	2	162
Trunk not opening	2017 June	23	1	138
Trunk will not open	2009 March	21	1	34
Vent window seal	2009 June	20	1	37
Windshield support rod	2016 March	22	4	124
Brakes				
Brake fluid disappearing	2012 December	23	1	89
Brake fluid type	2014 March	22	2	99
Brake repair	2009 December	19	1	47
Disc brake conversion	2014 June	26		105
Rear brakes pulsating	2010 June	21	1	57
Rear disc brake conversion	2014 March	22	1	99
Carburetion/Fuel System				
Air filter hose	2018 June	24	2	155
Carburetor manifold	2013 March	23	1	91
Carburetor repair	2010 December	21	1	65
Damper oil low	2008 December	20	1	29
Float levels	2018 September	22	3	157
Fuel filling engine	2008 October	21	1	26
Fuel pump pressure	2009 September	26	1	46
Fuel tank contaminants	2018 March	25		152
Gas type and additives	2016 March	22	2	124
Lead additive	2017 September	22	2	141
Old gas in tank	2012 March	23	3	83
Rebuilt fuel pump	2018 June	22	1	153
Sidedraft or downdraft Weber	2009 March	22		35
SU carbs leaking gas	2009 June	20	2	37
Zenith-Stromberg carb spring	2013 June	23	2	93

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION			PAGE NUMBER THIS ISSUE
	ISSUE	PAGE	Q&A	
Cooling/Heating System				
Cooling fluid loss	2017 December	25	1	147
Draining cooling system	2016 March	23	1	125
PSI radiator cap	2013 September	23	1	95
Radiator splash guard	2011 December	26	1	82
Electrical				
6 volt batteries and ground type	2012 March	26	1	84
Battery cable connection	2010 March	20	1	52
Brake light switch	2017 March	25	1	136
Brake lights not working	2018 March	24	1	151
Cut-off switch	2011 March	23	1	70
Front turn signal lamps	2010 March	28	1	56
Fusing the overdrive circuit	2018 June	24	1	155
Ignition key frozen	2015 June	22	1	115
Ignition key frozen (part 2)	2015 December	22	3	121
No electrical items	2015 December	22	3	122
No electricals	2010 December	22	2	66
No sound when turning ignition key	2016 September	24	1	131
No spark	2009 June	23	1	40
Rear lights lost	2018 December	22	1	161
Replace wiper motor	2008 May	19	1	18
Side marker lights	2010 September	21	2	61
Signal and headlight switches	2010 June	21	2	57
Starter not engaging	2015 March	23	1	113
Starter run on	2011 September	22	1	78
Starter spinning	2015 December	22	2	121
Switches	2008 February	19	1	11
Switches below radio	2016 June	22	1	127
Turn signal cancellation	2018 March	23	1	150
Voltage regulator	2017 September	22	1	141
Emission Controls				
California smog checks	2014 March	22	3	99
Catalytic converter	2015 March	22	2	112
Charcoal cannister foam	2018 March	24	2	151
Crankcase contaminates	2011 March	21	1	68
Detoxing the MGB	2018 September	24		159
PCV System	2015 December	26		123
Pollution control removal	2011 June	21	1	72
Ported vacuum source	2011 September	26	1	80
Smog emission test problem	2009 December	26	1	50
Engine/Mechanical				
Acceleration problem	2009 December	20	3	48
Backfiring	2014 December	22	1	109
Clicking noise when starting	2008 December	20	2	29

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION			PAGE NUMBER
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q&A</u>	<u>THIS ISSUE</u>
Compression test reading	2017 June	25	1	140
Cylinder head replacement	2010 March	22	1	54
Electronic ignition	2018 June	25		156
Engine missing	2018 March	23	2	150
Engine mounts & replacement	2017 September	23	1	142
Engine replacement	2017 June	22	2	137
Engine stalling	2015 December	22	1	121
Firing order	2017 June	25	1	140
Gasket type	2016 September	23	1	130
Heat shield	2014 December	22	2	109
Head gasket question	2016 March	22	1	124
Hesitation on acceleration	2011 June	21	1	72
Locktab	2017 December	23	1	145
Misfiring	2017 September	25	1	144
Oversized filter rings	2018 June	24	3	155
Rocker assembly removal	2017 December	25	2	147
Running rough	2017 December	23	2	145
Setting the vacuum advance	2008 December	22		31
Smoke from exhaust	2015 March	26	1	114
Solenoid switch	2009 December	20	2	48
Spark plug fouling	2017 September	22	3	141
Stainless steel exhaust	2016 March	22	3	124
Timing	2014 December	23	1	110
Timing (part 2)	2015 March	22	1	112
Tune - up guidelines	2017 June	23	2	138
Valves	2016 March	26	1	126
Exhaust				
Air manifold holes	2018 September	23	1	158
Gauges				
Fuel and temp gauge failure	2015 December	26	1	123
Oil pressure gauge	2009 September	20	1	42
Gauge readings	2018 March	22	2	149
Speedometer not working	2008 December	20	3	29
Speedometer drive leaking	2018 December	22	2	161
Tach reading high	2010 March	26	1	55
Tachometer inoperable	2017 June	22	1	137
General				
After storage	2018 September	23	2	158
Air conditioning	2018 June	22	2	153
Air conditioning load	2018 September	22	1	157
Buying an MGB	2013 September	23	2	95
Evaluating a non-running MG	2008 February	21		13
Fair price or MGB-GT	2010 September	22	1	62
Survival tools	2018 December	24		163

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION			PAGE NUMBER
	ISSUE	PAGE	Q&A	THIS ISSUE
Title issues	2012 March	23	2	83
Training manuals	2018 December	23	1	162
VIN number decoding	2013 June	23	1	93
Winter car wash	2011 March	26		71
Interior				
Dashboard Removal	2008 May	21		19
History or you MG	2010 June	26	1	59
Padded dash replacement	2016 March	23	2	125
Oil/Lubrication				
Correct oil filter	2008 October	20	1	25
Differential oil	2011 December	23	1	81
Drain plug oil drip	2008 October	22		27
Lack of oil pressure	2009 March	20	1	33
Normal oil pressure	2014 June	22	1	103
Oil filler cap replacement	2014 December	22	3	109
Oil pressure	2008 August	20	2	22
Suspension/Handling				
Front suspension	2018 June	25		156
Rear axle noise	2011 December	23	1	81
Rear axle bearings	2014 June	23	1	104
Rear end noise	2008 August	20	1	22
Shock conversion	2016 December	24	1	133
Steering items	2015 September	25	1	132
Steering rack boots	2014 September	23	1	107
Transmission/Handling				
Collar and hub wear	2017 December	26	1	148
Clutch burning and slippage	2011 June	26		74
Clutch peal soft	2015 September	22	1	118
Clutch pedal goes to floor	2017 March	24	1	135
Clutch release bearing noise	2017 March	24	2	135
Gearbox fit	2009 March	21	2	34
Overdrive not engaging	2018 March	22	1	149
Reverse gear problems	2012 September	23	3	87
Speedometer with overdrive	2008 February	20	1	12
Stiff steering	2013 December	23	1	97
Wheels/Tires				
Balancing Rostyle wheels	2011 September	21	1	77
Removing octagon knock-offs	2016 June	23	1	128
Tire size	2013 June	23	2	93
Wheel sizes	2010 March	21	1	53
Wire to disc wheel conversion	2014 March	26	1	100

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION			PAGE NUMBER
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q&A</u>	<u>THIS ISSUE</u>
Wire wheel basics	2012 September	23	1	87
Wire wheel conversion	2012 June	23	1	85
Wire wheel hubs	2018 September	22	2	157

