



AMERICAN MGB ASSOCIATION

TECHNICAL SECTIONS

VOLUME IV
(OCTAGON YEARS 2008 THRU 2017)

AVAILABLE IN CD AND PRINTED FORMATS

Volume I, II and III covering earlier publications also available from the AMGBA

PUBLISHED BY THE AMGBA
5433 N.ASHLAND AVE., CHICAGO, IL 60640 U.S.A.
Phone: (773) 878-5055
FAX: (773) 769-3240
email: info@mgclub.org
www.mgclub.org or www.amgba.com

AMGBA TECHNICAL SECTIONS VOLUME IV

<u>PUBLICATION</u>	<u>PAGE</u>
2008 February	9
2008 May	15
2008 August	20
2008 October	23
2008 December	27
2009 March	31
2009 June	35
2009 September	40
2009 December	45
2010 March	50
2010 June	55
2010 September	59
2010 December	63
2011 March	66
2011 June	70
2011 September	75
2011 December	79
2012 March	81
2012 June	83
2012 September	85
2012 December	87
2013 March	89
2013 June	91
2013 September	93
2013 December	95
2014 March	97
2014 June	101
2014 September	104
2014 December	107
2015 March	110
2015 June	113
2015 September	116
2015 December	119
2016 March	122
2016 June	125
2016 September	128
2016 December	131
2017 March	133
2017 June	135
AMGBA Regalia/Store Order Form	139
AMGBA Membership Application	140

NOTE: Please note the ads that may appear here are reproduced as they originally appeared in that issue and therefore may be several years old and are not to be relied on for prices or information.

Nothing may be reproduced in whole or in part without the written permission of the publisher. The views of contributing writers are their own and not necessarily the views of the AMGBA. Readers are warned in following any advice given and no liability either express or implied is assumed by the advice or opinions given by individual contributors or the AMGBA.

ARTICLE INDEX

Publication references in which AMGBA publication the article originally appeared and the year; the page number it was on and if a Question and Answer (Q&A), its position on the page and lastly the page number in this issue.

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION			PAGE NUMBER <u>THIS ISSUE</u>
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q&A</u>	
Body/Exterior				
Broken antenna replacement	2009 March	22		33
Door weather-stripping	2010 December	21	1	63
Floor board rust	2009 June	20	2	35
Floor panel and fender rust	2016 June	26	1	127
Grille replacement	2010 September	21	1	59
Installing a new top	2014 September	22	1	104
Rust preventatives on sills & floor pans	2009 September	23	1	43
Safety belt repair	2009 December	20	1	46
Overdrive emblems	2012 March	23	1	81
Rear bumper clamping bar	2013 June	23	2	91
Trunk not opening	2017 June	23	1	136
Trunk will not open	2009 March	21	1	32
Vent window seal	2009 June	20	1	35
Windshield support rod	2016 March	22	4	122
Brakes				
Brake fluid disappearing	2012 December	23	1	87
Brake fluid type	2014 March	22	2	97
Brake repair	2009 December	19	1	45
Disc brake conversion	2014 June	26		103
Rear brakes pulsating	2010 June	21	1	55
Rear disc brake conversion	2014 March	22	1	97
Carburetion/Fuel System				
Carburetor manifold	2013 March	23	1	89
Carburetor repair	2010 December	21	1	63
Damper oil low	2008 December	20	1	27
Fuel filling engine	2008 October	21	1	24
Fuel pump pressure	2009 September	26	1	44
Gas type and additives	2016 March	22	2	122
Old gas in tank	2012 March	23	3	81
Sidedraft or downdraft Weber	2009 March	22		33
SU carbs leaking gas	2009 June	20	2	35
Zenith-Stromberg carb spring	2013 June	23	2	91
Cooling/Heating System				
Draining cooling system	2016 March	23	1	123
PSI radiator cap	2013 September	23	1	93
Radiator splash guard	2011 December	26	1	80

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION			PAGE NUMBER THIS ISSUE
	ISSUE	PAGE	Q&A	
Electrical				
6 volt batteries and ground type	2012 March	26	1	82
Battery cable connection	2010 March	20	1	50
Brake light switch	2017 March	25	1	134
Cut-off switch	2011 March	23	1	68
Front turn signal lamps	2010 March	28	1	54
Ignition key frozen	2015 June	22	1	113
Ignition key frozen (part 2)	2015 December	22	3	119
No electrical items	2015 December	22	3	120
No electricals	2010 December	22	2	64
No sound when turning ignition key	2016 September	24	1	129
No spark	2009 June	23	1	38
Replace wiper motor	2008 May	19	1	16
Side marker lights	2010 September	21	2	59
Signal and headlight switches	2010 June	21	2	55
Starter not engaging	2015 March	23	1	111
Starter run on	2011 September	22	1	76
Starter spinning	2015 December	22	2	119
Switches	2008 February	19	1	9
Switches below radio	2016 June	22	1	125
Emission Controls				
California smog checks	2014 March	22	3	97
Catalytic converter	2015 March	22	2	110
Crankcase contaminates	2011 March	21	1	66
PCV System	2015 December	26		121
Pollution control removal	2011 June	21	1	70
Ported vacuum source	2011 September	26	1	78
Smog emission test problem	2009 December	26	1	48
Engine/Mechanical				
Acceleration problem	2009 December	20	3	46
Backfiring	2014 December	22	1	107
Clicking noise when starting	2008 December	20	2	27
Compression test reading	2017 June	25	1	138
Cylinder head replacement	2010 March	22	1	52
Engine replacement	2017 June	22	2	135
Engine stalling	2015 December	22	1	119
Firing order	2017 June	25	1	138
Gasket type	2016 September	23	1	128
Heat shield	2014 December	22	2	107
Head gasket question	2016 March	22	1	122
Hesitation on acceleration	2011 June	21	1	70
Setting the vacuum advance	2008 December	22		29
Smoke from exhaust	2015 March	26	1	112

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION			PAGE NUMBER THIS ISSUE
	ISSUE	PAGE	Q&A	
Solenoid switch	2009 December	20	2	46
Stainless steel exhaust	2016 March	22	3	122
Timing	2014 December	23	1	108
Timing (part 2)	2015 March	22	1	110
Tune - up guidelines	2017 June	23	2	136
Valves	2016 March	26	1	124
Gauges				
Fuel and temp gauge failure	2015 December	26	1	121
Oil pressure gauge	2009 September	20	1	40
Speedometer not working	2008 December	20	3	27
Tach reading high	2010 March	26	1	53
Tachometer inoperable	2017 June	22	1	135
General				
Buying an MGB	2013 September	23	2	93
Evaluating a non-running MG	2008 February	21		11
Fair price or MGB-GT	2010 September	22	1	60
Title issues	2012 March	23	2	81
VIN number decoding	2013 June	23	1	91
Winter car wash	2011 March	26		69
Interior				
Dashboard Removal	2008 May	21		17
History or you MG	2010 June	26	1	57
Padded dash replacement	2016 March	23	2	123
Oil/Lubrication				
Correct oil filter	2008 October	20	1	23
Differential oil	2011 December	23	1	79
Drain plug oil drip	2008 October	22		25
Lack of oil pressure	2009 March	20	1	31
Normal oil pressure	2014 June	22	1	101
Oil filler cap replacement	2014 December	22	3	107
Oil pressure	2008 August	20	2	20
Suspension/Handling				
Rear axle noise	2011 December	23	1	79
Rear axle bearings	2014 June	23	1	102
Rear end noise	2008 August	20	1	20
Shock conversion	2016 December	24	1	131
Steering items	2015 September	25	1	130
Steering rack boots	2014 September	23	1	105

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION			PAGE NUMBER
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q&A</u>	<u>THIS ISSUE</u>
Transmission/Handling				
Clutch burning and slippage	2011 June	26		72
Clutch peal soft	2015 September	22	1	116
Clutch pedal goes to floor	2017 March	24	1	133
Clutch release bearing noise	2017 March	24	2	133
Gearbox fit	2009 March	21	2	32
Reverse gear problems	2012 September	23	3	85
Speedometer with overdrive	2008 February	20	1	10
Stiff steering	2013 December	23	1	95
Wheels/Tires				
Balancing Rostyle wheels	2011 September	21	1	75
Removing octagon knock-offs	2016 June	23	1	126
Tire size	2013 June	23	2	91
Wheel sizes	2010 March	21	1	51
Wire to disc wheel conversion	2014 March	26	1	98
Wire wheel basics	2012 September	23	1	85
Wire wheel conversion	2012 June	23	1	83